

Mainline 6B 2012 Maintenance and Rehabilitation & Line 6B Replacement Projects
IDEM Water Quality Certification Independent Environmental Monitor Weekly Observation Report

Observation Dates:	03/31/14 thru 04/05/14
IEM Name:	Eric Sorenson
Waterbody Identification Number(s):	S-478-A, S-488-A, S-488-Y, S-489-Z, S-489-B, S-496-C
Wetland Identification Number(s):	W-485-A, W-478-F, W-486-C, W-488-Y, W-489-Y, W-469-A, W-499-A, W-496-Y
Enbridge Land Tract Identification Number(s):	N-619-11, N-613-6, N-621-2C-1, N-622-1A, N-622-10, N-622-10A-1, N-623-1A, N-631-7C, N-629-1
County(s): St. Joseph, LaPorte, Porter	Porter and LaPorte
<p>03/31/14: No contractor activity. 04/01/14: Pipeline contractor is performing repairs from punch list generated by environmental team. 04/02/14: No contractor activity. 04/03/14: Received information about land owner complaint concerning possible upland sediment in wetland. 04/04/14: Investigated landowner complaint about sediment in wetland. Concluded that upland sediment was coming from mats due to heavy rains at this location. 04/05/14: The contractor continues doing repairs as needed throughout the ROW.</p>	



Boyd property minor sediment from heavy rains from mats_E



W-478-F_Boyd upland soil possibly from mats_E



sta#1080+00_MP485.6_W-485-A_ECD'S in working order_E



sta#1152+00_MP486.9_W-486-C_ECD'S in working order_E



sta#1227+00_MP488.3_W-488-Y_ECD'S in working order_N



sta#1270+00_MP489.2_W-489-A_ECD'S in working order_NE



sta#1638+00_MP496.1_W-496-Y_ECD'S in working order_E



sta#1800+00_MP499.2_W-499-B_ECD'S in working order_W

